

Vehicle Diagnostic Report

The Report is created by **LAUNCH X-431**

Repair Shop

Shop Name:Tiptronic Car Maintenance

Address:Shop # 3 Sadaf Terrace Block # 7 Federal B Area Karachi Sindh

Zip Code:75950

Telephone:03218983878

Email:tiptroniccarsolutions@gmail.com

SN:989510023467

Test Time:2022-10-08 04:40:38



Vehicle Information

Year:2005

Make:Toyota

Model:Vitz

Odometer:90501.00

Vehicle Software Version:V50.45

Diagnostic Application Version:V7.05.016

Diagnostic path:16PIN DLC(Japan) > Vitz > 1KR-FE > 2007.08-2008.07



System fault code

The following system is abnormal:

Engine 2 problems exist

1.P1550 Battery Current Sensor Circuit	Pending
2.P1602 Deterioration of Battery	Pending

ABS/VSC/TRC(TRAC) 3 problems exist

1.C1241 Low or High Power Supply Voltage	Current
2.C1425 Open in Stop Switch Circuit	Current
3.U0073 Control Module Communication Bus Off	Current

SRS Airbag 8 problems exist

1.B1826 Open in Side Squib(LH)Circuit	Current
2.B1836 Open in Curtain Shield Airbag(LH)Squib Circuit	Current
3.B1905 Short in Pretensioner Squib(LH)Circuit	Current
4.B1648 Side Satellite Sensor Bus Initialization Error(LH)	Current
5.B1826 Open in Side Squib(LH)Circuit	History

6.B1836 Open in Curtain Shield Airbag(LH)Squib Circuit	History
7.B1905 Short in Pretensioner Squib(LH)Circuit	History
8.B1648 Side Satellite Sensor Bus Initialization Error(LH)	History

Air Conditioner 1 problem exist

1.B1412 Ambient Temperature Sensor Circuit	Current
--	---------

Main Body 2 problems exist

1.B2321 Driver Door Motor ECU Communication Stop	History
2.B2325 LIN Communication Bus	History

D-Door Motor 1 problem exist

1.B2312 Master Switch of Driver side door Malfunction	History
---	---------

The following systems are OK:

- 1.EMPS
- 2.Combination Meter